


Bare-skim is for use on naked skin. Use Bare-skim on dry or damp skin. For best results skin should be as dry as possible. With the aid of Bare-skim most people can get a tech suit fully on within 15 minutes or less.




1.
Fasten Bare-skim around waist & ankles.
Follow instructions on the tech suit.



2.
Pull suit up each leg then up to waist.
Ankle fasteners may come apart.



3.
Adjust suit over Bare-skim as needed.
Detach & roll ankle fasteners up in
material, tuck-up under knees of suit
to each side.



4.
With tech suit over the waist,
fold top of suit straight down over
the hips.



5.
Unfasten waist and gather Bare-skim
to each side. Pull Bare-skim up and
out at each side.



6.
Continue with tech suit instructions
for chest & arms.